

| | | | | | |
|---|---|---|---|---|---|
| DRAWN | - - | | FACOM | | |
| CHECK | 08-04-92 | MGM | DRAR | 1080 | 11-08-92 |
| DESIGN | 08-31-92 | MTT | ZONE | NONE | |
| REVISION | 08-31-92 | MTT | TYPE | 5200 | |

WIRE LIST OF TLA4
WIRE LIST OF 2ND TLA4

ZONE 1

INTERNATIONAL BUSINESS MACHINES CORP.

NOTES:

01-ALL CIRCUIT WIRE COMPONENT TO BNC*2SEC* SHOWN ON SHEET 1*
02-SEE INSTRUCTION 8E0043
03-SEE ENGINEERING SPECIFICATION 8E0043
04-CARD COMPONENT TO DECOUPLING REQUIREMENTS IN 8J7800*
05-MIN BNC 8J7121 TO 4-10-24 2PCER*
06-MIN BNC 8J7122 TO 4-10-24 2PCER*

| PIN | ADDR | PIN | ADDR |
|---|---|---|---|
| 1 | 0/0 | 2 | 0/1 |
| 3 | 0/2 | 4 | 0/3 |
| 5 | 0/4 | 6 | 0/5 |
| 7 | 0/6 | 8 | 0/7 |

| PIN | CODE | WIRE NO | NOTE | PIN |
|---|---|---|---|---|
| 1 | DC | 8J7128 | | 2 |
| 3 | DWG ZEO | 3J8252 | | 4 |
| 5 | DWG ZEO | 3J8253 | | 6 |
| 7 | NWA NWA | 2J8002 | | 8 |
| 9 | 2F1 MODULE | 3J8026 | | 10 |
| 11 | BC MODULE | 5J6001S | | 12 |
| 13 | BC MODULE | 5J6005S | | 14 |
| 15 | BC MODULE | 5J6008S | | 16 |
| 17 | BC MODULE | 5J6009S | | 18 |
| 19 | BC MODULE | 5J6010S | | 20 |
| 21 | BC MODULE | 5J6015S | | 22 |
| 23 | BC MODULE | 5J6020S | | 24 |
| 25 | | 8J7126 | | 26 |
| 27 | | 8J7127 | | 28 |

| | | | | |
|---|---|---|---|---|
| 2B4B0B5 | | | | |
| BACK MATRIX | | | | |
| 2B4B0B5 | 08-30-92 | 1000000 | P1 | |
| LOGIC MATRIX | DATE | CHANGE NO* | DATE | CHANGE NO |
| MAP CARD NUMBER | 2B4B0B5 | | HOLE MATRIX | 2B4B0B5 |
| PRODUCTION | LEVICE | | | RESTRICTED |
| CONFIG MANAGER | | - - | 2J0792 | PRIVATE |
| STANDARD CODE | 9-1042 | | SHEET 5 OF 5 | 2B0T2E4 |