


STANDARDS CODE	2-70-5			5800735
CIRCUIT APPROVAL	IE	08-11-64	STATUS	ACTIVE
LOCATION	SAN JOSE			RESTRICTED
RAW CARD NUMBER	5816880 01		HOLE PATTERN	5816880
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO
5816880	07-21-64	160537		
BACK ARTWORK	08-17-64	161270		
5816880	01-30-65	163085		

PIN	VOLT.
D03	+12
B06	0R
B11	12V

CODE	PART NO	VALUE	QTY
R 1	216457	3.600K ±25 + 5	2
Q 1	369686	178 NPN	4
Z 1	361492	SLT MODULE	4
HA	811157	SPACER	4

NOTES:
AA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.
AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
AL-CARD HAS NOT BEEN DECOUPLED. 811800 IS NOT APPLICABLE.
FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.
ADDITIONAL USAGE TO BE AVOIDED
HA-ASSEMBLE WITH PIN 811157 PTO-18, SPACER.



INTERNATIONAL BUSINESS MACHINES CORP.					
NAME	RELAY DRIVER				
DESIGN	07-23-64	TH	TYPE	1070	
DETAIL	07-23-64	TH	SCALE	NONE	
CHECK	08-11-64	PC	DRAW	7090	10-21-64
APPRO	08-11-64	SAS	SHEET	2 OF 3	