






01 02
33 21
10 A 2

01 02
48 23
7 A 2

02 01
63 23
5 A 2



CONTACTS ON
BACK OF CARD

STANDARDS CODE	2-7045			5803037
CIRCUIT APPROVAL	URL	07-16-64	STATUS	ACTIVE
LOCATION	ENDICOTT			RESTRICTED
RAW CARD NUMBER	5819461		HOLE PATTERN	5819461
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5819461	10-13-64	161821		
BACK ARTWORK				
5819461				

PIN	VOLTS
D 8	0.10
D 3	+ 3
B 11	+ 6
B 6	- 3

CODE	PART NO	VALUE	QTY
DL 1	2391038	V 350	1
DL 2	2391035	V 125	1
Z 1	361453	SLT MODULE	2
Z 2	361473	SLT MODULE	2
A 1	2390419	RC MODULE	1
A 2	2414883	RC MODULE	3

NOTES:
 AA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.
 AB-ASSEMBLE TO ENGINEERING SPECIFICATION 690913
 AC-CARD HAS BEEN DECOUPLED BY 1800 IS NOT APPLICABLE.
 AD-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.
 ADDITIONAL USAGE TO BE AVOIDED

INTERNATIONAL BUSINESS MACHINES CORP.				
DATE	1	DELAY CARD	-125NS +350NS	LM
DESIGN	109-23-64	TYPE	12030	
DETAIL	109-30-64	VRD	SCALE	NOVE
CHECK	110-06-64	WOT	DRCL	17090 110-22-64
ADDDQ	-		SHEET	2 OF 3