






STANDARDS CODE	2-7045	SHEET 2 OF 31 5803039		
CIRCUIT APPROVAL	NR	07-22-64	STATUS	ACTIVE
LOCATION	ENDICOTT			APPROVED
RAW CARD NUMBER	5815950	1	HOLE PATTERN	5815950
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5815950	07-22-64	DEV3543	02-09-67	169843 JC
BACK ARTWORK	11-24-64	161278		
5815950	03-24-65	163741	181	

PIA	VOLT.
D 6	010
D 3	+ 3
811	+ 6
8 5	- 1

CODE	PART NO	VALUE	QTY
Z 1	361454	SLT MODULE	4
Z 2	361451	SLT MODULE	4
R 1	2390410	RL MODULE	2

NOTES:

- RA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.
- RB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
- RA-CARD DOES NOT CONFORM TO DECOUPLING REQUIREMENTS IN 811800.



INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	4 RPL MULTIPLEX TERMINATED LIN			
E DRIVERS.				
DESIGN	06-20-64	LIN	TYPE	2030
DETAIL	06-24-64	LIN	SCALE	NONE
CHECK	06-25-64	DRW	DATE	102-10-67
APPRO	- -	LoCoNo	UNAPPROVED	