





NOTE
X THESE PINS SHOULD BE CONNECTED FOR
PROPER CIRCUIT OPERATION
D04 TO B04
B07 TO D07
NO BUSSING CONDITION EXISTS

INTERNATIONAL BUSINESS MACHINES CORP.					
NAME		DATE	CHANGE NO.	APPROVAL	
TDE-2		5-8-64	DEV 3361		
OSFORM LHM	H-1-64	MODEL	3-1-65	162N70/A	
DETAIL CDS	H-1-64	SCALE	NONE	18APR66S	
CHECK D/LN	H-1-64	DRAW	VE	3-12-65	
APPROB RMT	H-1-64	CHECK			