

STANDARDS CODE	2-7045		SHEET 2 OF 4	5803220
CIRCUIT APPROVAL			STATUS	ACTIVE
LOCATION	ENDICOTT			APPROVED
RAW CARD NUMBER	5814191	5	HOLE PATTERN	5814191
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5814191	11-05-64	160590	A	
BACK ARTWORK	03-30-66	164841	B	
5814191	07-25-66	168451	C	

PIN	VOLT.
D08	GND
D03	+03

CODE	PART NO.	VALUE	QTY
Z 1	361459	SLY MODULE	3
A 1	2390698	RC MODULE	10






NOTES.

AA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.

AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913

AC-NO SOLDER IN HOLES LOCATED AT X028Y0800X028Y0930X033Y0800
X033Y0930X038Y0800X038Y0930X043Y0800X043Y0930X048Y0800X048
Y0930X053Y0800X053Y0930X058Y0800X058Y0930X063Y0800X063Y0930
X068Y0800X068Y0930X073Y0800AND X073Y0930.

AD-CARD DOES NOT CONFORM TO DECOUPLING REQUIREMENTS IN 811800.



INTERNATIONAL BUSINESS MACHINES CORP.					
NAME	INDICATOR TERMINATOR				
DESIGN	10-14-64	W P	TYPE	2070	
DETAIL	03-01-66	JRB	SCALE	NONE	
CHECK	02-01-66	PAS	DRAW	17090	07-21-66
APPRO	- -		LoCNo		