

STANDARDS CODE	2-6235		SHEET 2 OF 3	5803754
CIRCUIT APPROVAL	ASD	12-05-67	STATUS	ACTIVE
LOCATION	SAN JOSE			RESTRICTED
RAW CARD NUMBER	5819382	2	HOLE PATTERN	5819382
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5819382	10-20-64	161412	1A	
BACK ARTWORK	12-01-65	167062	1B	
5819382	12-07-67	172661	1C	

PIN	VOLT.

CODE	PART NO	VALUE	QTY
R 1	216436	390.000 .25 + 5	2
R 2	216434	330.000 .25 + 5	1
R 3	550049	82.000 .25 + 5	1
CR 1	2106333	ALS	4
CR 2	492496	BLS	1
CR 3	369388	DL	1
Q 1	369686	178 NPN	1
Q 2	369113	047 PNP	1
RR 1	766040	NO-01 NC-00	2
FN	815198		12
HA	811157	PTO-18 ₁ SPACER.	101
HB	811399	PTO-5 ₁ SPACER.	101

NOTES.

AA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.

AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913

AL-CARD HAS NOT BEEN DECOUPLED. 811800 IS NOT APPLICABLE.

AM-ADDITIONAL COATING TO BE APPLIED PER ENG. SPEC 876805


AN-CONTACTS PIN 815198 TO BE INSERTED BEFORE LIQUID PROCESS PER

ENG. SPEC. 8711830 REED RELAY ASSEMBLY TO BE HAND MOUNTED ON

CONTACTS AFTER LIQUID PROCESS.

HA-ASSEMBLE WITH PIN 811157 PTO-18₁ SPACER.

HB-ASSEMBLE WITH PIN 811399 PTO-5₁ SPACER.



INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	OVERLOAD SWITCH			
DESIGN	09-01-64	PCY	TYPE	1070
DETAIL	11-18-67	PH	SCALE	NONE
CHECK	11-20-67	TPH	DRAW	7090 11-13-57
APPRO	11-20-67	SMS	LSG	