



BD		N 02207	01A01	B04	I J12	25203	0 32211	G10 BL4	N 21211	20A04	N 25209	19205	22	
0921	06A01	N 03211	01A04	3225	2524	I J12	32207	BK4	2121	20A1	N 19207	18A01	V 06	+6V
I D07	09203	N 03211	21204	BH4	I G13	32206	3023		2524	B04	N 19211	18A01	V 10	+6V
N 09207	06A01	BF4		3225	2524	I J11	32209	I G13	30207	I G02	21202	1921	D13	23
N 09211	06A04					I J11	32209	I J11	30202	I 09211	21203	2524	V 05	+6V
0 09211	21203	I B03	07204	3225	31A03	N 25204	32205	I 099	30201	I 09211	21204	I B03	25210	21
BE4		N 07207	06A01	I G12	32203	N 25207	32206	I J13	30204	I 07211	21204	I B03	19202	V 06
0921	01A1	N 07211	06A04	I J11	32202	N 32212	31A03	N 30211	30212	N 25202	21205	I D07	19201	V 08
I D05	09204	0 07211	05A01	I G13	32204	N 32211	21A04	0 30203	32210	N 21207	20A01	I J04	19204	V 12

06-12-64 DEV:3622
08-5-64 161139
+3V

SHIFTER OVERFLOW

DATE 00-00-00 MACH. ASSEMBLY

LOG 150A FRAME

CD PG 2 OF 2 P.N. 05004124

IBM CORP. PD BLK. BU

4
1
2
4
2
000