

STANDARDS CODE	2-7045	SHEET 2 OF 4	5804649
CIRCUIT APPROVAL	JCR	09-08-66	STATUS
LOCATION	BOLDER		RESTRICTED
RAW CARD NUMBER	5817834	1	HOLE PATTERN
FRONT ARTWORK	DATE	CHANGE NO.	DATE
5817834	06-04-65	164389	A
BACK ARTWORK	12-27-66	166532	B
5817834			

PIN	VOLT.	PIN	VOLT.	CODE	PART NO	VALUE	QTY
Q12	-30	J08	GND	R 1	550050	1240.000	.25 + 5 4
D08	GND	G06	-03	R 2	216424	68.000	.25 + 5 4
D03	+03	B08	GND	R 3	595358	270.000	.25 + 5 2
G11	+06	B11	+06	R 4	595359	100.000	.25 + 5 4
J09	GND	B06	-03	CR 1	2414891	GV	24
J03	+03	D12	GND	Q 1	2390103	268 NPN	8
G09	GND			HS 1	813193	HEAT SINK	8
				T 1	2391146	PULSE TRANSFORMER	4
				T 2	2391188	PULSE TRANSFORMER	4
				T 3	2390107	PULSE TRANSFORMER	4
				Z 1	361468	SLT MODULE	2
				Z 2	361406	SLT MODULE	2
				A 1	2414863	RC MODULE	8
				A 2	2390577	RC MODULE	2
				PA			10
				FX	483151		00
				HB	611399		08

NOTES:
 RA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.
 AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890413
 AK-CARD HAS BEEN DECOUPLED 811800 IS NOT APPLICABLE.
 FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.
 ADDITIONAL USAGE TO BE AVOIDED
 FX-MOUNT HEAT SINK USING SI GREASE (P/N 483151) ON THE TRANSISTOR CAN. SI GREASE MUST BE APPLIED AFTER LIQUID PROCESS.
 HB-ASSEMBLE WITH P/N 611399 PTO-S4 SPACER.

INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	SOURCE DRIVER			
DESIGN	03-31-65	GFP	TYPE	AD030
DETAIL	04-01-65	J L	SCALE	NONE
CHECK	10-04-66	JRB	BRW	7090
APPRO	-	-	L.C.N.	LAPINATED

