

SPECIAL REWORK DRAWING

REWORK ALL ASSEMBLIES BY REVERSING MODULE 24A8 OF 5804661 SO THAT
PIN 1 IS LOCATED AT X98/Y68 AND PIN6 AT X123/Y68.
REMOVE 5804661 ON SOLDER SIDE OF CARD AND STAMP HOUSING WITH P/N
5800878 E/C 167079/B.

165491/C

NOTE: THIS E.C. ~~165491/C~~ IS TO FACILITATE REWORKING OF ALL STOCK
OF 5804661 INTO 5800878 E/C 167079/B. UPON DEPLETION OF
STOCK, 5804661 IS TO BECOME OBSOLETE.

COMPONENTS HAVE BEEN RENUMBERED TO AGREE WITH 5800878 E/C 167079/B.

MARKED PRINT 24 MAY 66
FILE IN PLACE OF 162381/B
TEST TO 167079/B