

STANDARD CODE	2-7045	SHEET 2 OF 61 168754		
CIRCUIT APPROVAL	GM	10-10-66	STATUS	ACTIVE
LOCATION	POUGHKEEPSIE			APPROVED
REL CARD NUMBER	5817483	3	HOLE PATTERN 5817483	
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5817483	10-13-66	168753	3	
BACK ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5817483	10-10-66	168754	01	

PIN	VOLTS
011	+ 5
011	+ 6
008	GND
008	GND
006	- 5
007	-25

CODE	PART NO.	VALUE	QTY
R 1	216450	1.000K	25 + 5 5
R 2	216444	910.000	25 + 5 2
R 3	216423	62.000	25 + 5 4
R 4	2390116	40.000	4.50 + 1 1
R 5	216424	6.000	25 + 5 4
R 6	483179	1.000	25 + 5 6
R 7	216434	330.000	25 + 5 2
CR 1	2414691	OV	26
Q 1	2390103	268 JPN	8
HS 1	813193	HEAT SINK	3
T 1	2390107	PULSE TRANSFORMER	4
T 2	2391146	PULSE TRANSFORMER	4
Z 1	361468	SLT MODULE	6
A 1	2390469	RC MODULE	2
A 2	2414883	RC MODULE	5
PA			34
PK	483151		00
HB	811399		04

NOTES:
 HB-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.
 HB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913.
 PK-CARD HAS BEEN DECOUPLED 811900 IS NOT APPLICABLE.
 PA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.
 ADDITIONAL USAGE TO BE AVOIDED.
 PK-MOUNT HEAT SINK USING SI GREASE (P/N 483151) ON THE TRANSISTOR CASE. SI GREASE MUST BE APPLIED AFTER LIQUID PROCESS.
 HB-ASSEMBLE WITH P/N 811399 PTO-51 SPACER.

