

STANDARDS CODE	2-7045			5804836
CIRCUIT APPROVAL		- -	STATUS	ACTIVE
LOCATION	ENDICOTT			RESTRICTED
RAW CARD NUMBER	5818835		HOLE PATTERN	5818835
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO
5818835	10-07-64	161017		
BACK ARTWORK				
5818835				

PIN/VOLT.	PIN/VOLT.	CODE	PART NO	VALUE	QTY
G11 +06	J08 GR	N 1	5301517	10.000 .25 + 5	1
G06 -03	G04 +18	CR 1	2414884	GT	1
J03 +03	E11 +06	Q 1	369586	178 NPN	1
D08 GR	B06 -03	DL 1	2414941	N 730	3
D03 +03		Z 1	361473	SLT MODULE	2
		Z 2	361459	SLT MODULE	1
		Z 3	361457	SLT MODULE	1
		A 1	2414883	RC MODULE	13
		A 2	2390445	RC MODULE	1
		A 3	2390459	RC MODULE	1
		A 4	2390476	RC MODULE	1
		A 5	2390690	RC MODULE	1
		A 6	2390616	RC MODULE	1
		A 7	2390673	RC MODULE	1
		HA	811157		02

NOTES:

RA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.

AB-ASSEMBLE TO ENGINEERING SPECIFICATION 690913

AK-CARD HAS BEEN DECOUPLED 811800 IS NOT APPLICABLE.

FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.

ADDITIONAL USAGE TO BE AVOIDED

HA-ASSEMBLE WITH PIN 811157 PTO-184 SPACER.

HD-HAND ASSEMBLE BEFORE LIQUID PROCESS.

HA-PART MUST NOT BE SUBJECTED TO ANY LIQUID.

INTERNATIONAL BUSINESS MACHINES CORP.					
NAME	R2 CLOCK DELAY				
	LAP				
DESIGN 112-21-63	H	TYPE	1101		
DETAIL 09-10-64	VAD	SCALE	NONE		
CHECK 09-24-64	WDF	DATE	7090	110-02-64	
APPRO	- -		SHEET 2 OF 5		

01
28183

03

05

07

09

11

01
28143

02

03

04

05

06

07

08

09

10

11

12
138143

5804836

4DL 1 / 16