

STANDARDS CODE	2-7045		SHEET 2 OF 4	5804985		
CIRCUIT APPROVAL	GMA	11-12-65	STATUS	ACTIVE		
LOCATION	POUGHKEEPSIE			RESTRICTED		
RAW CARD NUMBER	5816509	2	HOLE PATTERN	5816509		
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.		
5816509	05-27-65	162182	A	03-21-66	167341	D
BACK ARTWORK	11-12-65	166166	B			
5816509	12-15-65	166164	C			

PIN	VOLT.	PIN	VOLT.	CODE	PART NO	VALUE	QTY
D08	GND	J08	GND	R 1	813220	90.000 5.00 + 1	8
D03	+ 3	D13	-25	R 2	317032	1.000K 1.00 + 5	2
B11	+ 6	B06	- 3	R 3	48317	18.000 .25 + 5	2
J03	+ 3	G06	- 3	R 4	481	11.000 .25 + 5	2
Q11	+ 6			R 5	4926	200.000 .25 + 5	4
				R 6	21644	910.000 .25 + 5	2
				R 7	478991	28.000 .12 + 1	4
				B	332585	560.000 2.00 + 5	2
				C 1	492469	1.0 N	2
				Q 1	2391155	289 NPN	4
				L 1	491218	2.2 U	4
				T 1	2391154	PULSE TRANSFORMER	2
				T 2	2391270	PULSE TRANSFORMER	2
				A 1	2414883	RC MODULE	4
				FA			6
				HA	811157		04

NOTES:

AA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.

AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913

AZ-MOUNT R1 RESISTORS .075+ OR -.040 UP OFF CARD SURFACE. DUE TO COMPONENT HEIGHT OF .370 TO .4600 THIS CARD MUST BE REMOVED PRIOR TO REMOVAL OF CARD ADJACENT TO COMPONENT SIDE.

AK-CARD HAS BEEN DECOUPLED 811800 IS NOT APPLICABLE.

FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.

ADDITIONAL USAGE TO BE AVOIDED

HA-ASSEMBLE WITH PIN 811157 PTO-104 SPACER.

NA-PART MUST NOT BE SUBJECTED TO ANY LIQUID.

INTERNATIONAL BUSINESS MACHINES CORP.					
NAME	CARD ASM-LCS BUFFER + READ AND WRITE BIT RESISTORS				
DESIGN	11-12-65	ADC	TYPE	2361	
DETAIL	11-12-65	ADC	SCALE	NONE	
CHECK	11-19-65	ADC	DRAW	17090	- -
APPRO	11-12-65	GMA	LOCN	5804985A	LAMINATED

