

399
MONTHLY DATA DUMP

This location is called by FRN 1000 at the first of the month to dump a tape of last months data. After instructions are given it loads last months data that is stored in the daily data file into COM and SLINKS to the assembly language portion of the Save Data routine (see ET-9500-97003-1). After the data is dumped, the tpae is then verified. The routine then stores the monthly data file, which contains only 1 days worth of data via FRN 1000, into the daily data file to set the files equally ready for the next days data. The next and last function the routine performs is to set up the data in COM necessary for the Fraction Defective program. A LINK is then made to it (see ET 9500-97013-1)

				MODEL	STK NO
				BY Bill Birdsell	DATE 12-20-74
				APPD	SHEET NO 1 OF 1
LTR	PC NO	APPROVED	DATE	SUPERSEDES	DWG NO A-ET 9500-97007-1
REVISIONS					