



PRODUCTS BULLETIN

August 1976

9869A CARD READER

by Raja Segal

9869A Service Kit

(HP 40201A Optical Mark Reader Service Kit)

Here is another sales tool for you to sell 9869's. For your customers who would like to do their own thing as far as 9869 service is concerned, a service kit is now available. The kit will prove most valuable for customers who operate in remote areas and/or have facilities for their own service.

Features

- Spare modules and parts for on-site repair
- Maintenance and operating documentation
- Diagnostic programming documentation
- Rugged foam-lined carrying case
- Special maintenance tools

Spare Modules

A basic set of replacement modules for the 9869 is included in the 40201A Service Kit. Additional optional modules can be added to the kit to match specific models. All modules are factory tested before shipment and are warranted by Hewlett-Packard for 90 days.

Documentation

A service manual is shipped with each kit. It contains detailed installation and hardware configuration instructions, functional theory of operation, adjustment routines, troubleshooting information, removal, and replacement procedures. It includes all circuit diagrams and replacement parts lists.

Carrying Case

All service kit items are contained in a rugged carrying case.

Case features include:

- Reinforced corners
- Rivet-attached carrying handles
- Custom moulded internal cushions

Module Exchange Program

Hewlett-Packard operates an extensive assembly exchange program. Many of the modules in the Optical Mark Reader (OMR) kits are included in the Blue Stripe program. The program provides a low-cost means of obtaining a rebuilt assembly in exchange for an identical, defective, repairable assembly. Each exchange assembly is rebuilt to original factory specifications and carries the same warranty as an equivalent new part.

Significant replacement parts cost savings can be realized through use of the Blue Strip program.

Ordering Information

Model Number	Description	Price (U.S.)
HP 40201A	OMR Customer Service Kit. Contains basic modules, spare parts, and tools common to 7260A, 7261A, 12986A, 9869A Readers. Also contains carrying case.	\$ 1530
Opt. 004	Boards specific to 9869A (includes Encoder capability).	\$ 985

North American and ICON sales offices should order from Boise Division; European sales offices should order from Grenoble.

The 40201A Customer Service Kit is listed in the Corporate Price List and may be quoted immediately.