

STANDARDS CODE	2-7044			5803466
CIRCUIT APPROVAL	IE	08-07-64	STATUS	ACTIVE
LOCATION	SAN JOSE			RESTRICTED
RAW CARD NUMBER	5816595	1	HOLE PATTERN	5816595
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5816595	J1-17-64	DEV2118		
BACK ARTWORK	09-03-64	161244		
5816595	07-08-65	162723		

PIN	VOLT.
806	-03
811	+06
803	+03
808	GR

CODE	PART NO	VALUE	QTY
Z 1	361451	SLT MODULE	9
Z 2	361473	SLT MODULE	1
A 1	2414883	RC MODULE	3

NOTES:


AA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.

AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913

AK-CARD HAS BEEN DECOUPLED 811800 IS NOT APPLICABLE.

FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.

ADDITIONAL USAGE TO BE AVOIDED



CONTACTS ON
BACK OF CARD

INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	9 2-WAY AND + POWER INVERTER			
	LAP			
DESIGN	08-13-64	RT	TYPE	11430
DETAIL	08-13-64	RT	SCALE	NONE
CHECK	08-21-64	JH	DATE	11-18-64
APPRO	08-21-64	SAS	SHEET	2 OF 3