

STANDARDS CODE	2-7045		SHEET 2 OF 3	5803491
CIRCUIT APPROVAL	W.L.	02-20-67	STATUS	ACTIVE
LOCATION	BOULDER			RESTRICTED
RAW CARD NUMBER	5817000	02	HOLE PATTERN	5817000
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5817000	10-08-64	DEV2772	04-04-67	7 C
BACK ARTWORK	02-26-65	162864	14	
5817000	06-04-65	164537	18	

PIN	VOLT.
D03	+03
B06	-03
D08	GR
B11	+06

CODE	PART NO	VALUE	QTY
R 1	216443	750.000 .25 + 5	1
R 2	216436	390.000 .25 + 5	1
R 3	550051	51.000 .25 + 5	1
R 4	492615	200.000 .25 + 5	1
R 5	217081	130.000 .25 + 5	2
F 6	483119	2.000K 1. + 5	1
R 7	483219	1.000K .45 + 1	1
R 8	216431	180.000 .25 + 5	2
R 9	216433	300.000 .25 + 5	1
R10	483224	36.000 .25 + 5	2
R11	550049	82.000 .25 + 5	1
R12	216439	910.000 .25 + 5	1
R13	216449	1.500K .25 + 5	1
R14	216452	2.000K .25 + 5	1
R15	216461	5.100K .25 + 5	1
R16	492678	1.000K 1. + 5	1
CR 1	369593	DN	1
CR 2	2414891	GV	1
Q 1	369682	131 PNP	3
Z 1	361473	SLT MODULE	1
Z 2	361457	SLT MODULE	1
Z 3	361459	SLT MODULE	1
Z 4	361475	SLT MODULE	1
A 1	2414883	RC MODULE	4
A 2	2414920	RC MODULE	1
A 3	2390501	RC MODULE	1
FA			6
HA	811157	PTO-18 ₁ SPACER.	03

NOTES:

- AA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.
- AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
- AK-CARD HAS BEEN DECOUPLED 811800 IS NOT APPLICABLE.
- FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.
- ADDITIONAL USAGE TO BE AVOIDED
- HA-ASSEMBLE WITH PIN 811157 PTO-18₁ SPACER.
- NA-PART MUST NOT BE SUBJECTED TO ANY LIQUID.

INTERNATIONAL BUSINESS MACHINES CORP.					
NAME	VOLTAGE REFERENCE AND SENSE				
CONTROL					
DESIGN	02-11-65	RT	TYPE	SJM554	
DETAIL	02-11-65	RT	SCALE	NONE	
CHECK	02-12-65	PRH	DRW	7090	04-11-67
APPRO	02-12-65	SRS	LoCoNo		

