

STANDARDS CODE	2-7045		SHEET 2 OF 3	9800827
CIRCUIT APPROVAL	JES	03-02-65	STATUS	ACTIVE
LOCATION				RESTRICTED
ASB CARD NUMBER	5819239		HOLE PATTERN	5819239
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5819239	03-19-65	163122		
BACK ARTWORK				
5819239				

PIN	VOLT.	PIN	VOLT.	CODE	PART NO	VALUE	QTY
D11	+36	D12	+36	R 1	334947	1.800K 1.00	5 1
B11	+ 6	D03	+ 3	R 2	216993	1.300K 2.00	5 1
B06	- 3	D08	GND	R 3	216465	7.500K .25	5 1
D04	-36	D05	-36	R 4	216435	360.000 .25	5 1
				R 5	317025	6.800K .50	5 1
				R 6	216436	390.000 .25	5 1
				R 7	216460	4.700K .25	5 1
				CR 1	2414891	GY	1
				Q 1	318324	033 PNP	2
				Q 2	2414918	138 PNP	1
				Z 1	351473	SLT MODULE	1
				A 1	2414883	RC MODULE	5
				FR			2
				HB	811399	Spacer	03

NOTES:

RA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.

AS-ASSEMBLY TO ENGINEERING SPECIFICATION 890913

AK-CARD HAS BEEN DECOUPLED 811800 IS NOT APPLICABLE.

QA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.

ADDITIONAL USAGE TO BE AVOIDED

HB-ASSEMBLY WITH P/N 811399 PTO-5-1 SPACER.

INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	CARD ASB ASYNCHRONOUS DELAY			
EARLY BLANK SIGNAL				
DESIGN	01-29-65	NIS	TYPE	2290
DETAIL	01-29-65	NIS	SCALE	NONE
CHECK	02-19-65	R25	DRW	7090
APPROV	03-02-65	JES	LoCoNo	- -

