


STANDARDS CODE	2-7045			5801229
CIRCUIT APPROVAL	JLS	01-11-65	STATUS	ACTIVE
LOCATION	SAN JOSE			RESTRICTED
RAW CARD NUMBER	5817047		HOLE PATTERN	5817047
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5817047	01-25-65	162856		
BACK ARTWORK				
5817047				

PIN	VOLT.
DO8	GND
JO8	GND

CODE	PART NO	VALUE	QTY
R 1	216464	6.800K ±25 + 5	4
R 2	216491	100.000K ±25 + 5	1
C 1	483071	1. U	1
Q 1	369119	044 PNP	4
T 1	2174243	PULSE TRANSFORMER	1
T 2	2174242	PULSE TRANSFORMER	1
HB	811399	SPACER	4

NOTES.

- AA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.
- AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
- AL-CARD HAS NOT BEEN DECOUPLED. 811600 IS NOT APPLICABLE.
- FB-CARD REQUIRES 1.250 SPACING ON FRONT SIDE.
- HB-ASSEMBLE WITH P/N 811399 10-51 SPACER.



INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	400 CPS DEMOD			
DESIGN	11-19-64	RT	TYPE	2321
DETAIL	11-19-64	JEB	SCALE	NONE
CHECK	01-16-65	HVH	DRAW	7090 10-21-64
APPRO	01-16-65	SMS	SHEET	2 OF 3