

STANDARDS CODE	2-4235		SHEET 2 OF 4	5801447
CIRCUIT APPROVAL	PMS	06-16-67	STATUS	ACTIVE
LOCATION	POUNKEPSIE			RESTRICTED
RAW CARD NUMBER	5817980	1	HOLE PATTERN	5817980
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5817980	07-11-67	171625	A	
BACK ARTWORK	08-12-68	178385	B	
5817980				

PIN	VOLT.
D 8	GND
D 3	+ 3
B 11	+ 6
B 6	- 3

CODE	PART NO	VALUE	QTY
A 1	2414811	193 NPN	5
Z 1	361488	SLT MODULE	5
A 1	2414920	RC MODULE	5
A 2	2390435	RC MODULE	4
A 3	2390450	RC MODULE	2
PA			5
HS	815192		05

NOTES:

AA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.


AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913

AK-CARD HAS BEEN DECOUPLED 811800 IS NOT APPLICABLE.

PA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.

ADDITIONAL USAGE TO BE AVOIDED

HS-ASSEMBLE WITH P/N 815192 PTO-104 INSULATING SPACER



CONTACTS ON
BACK OF CARD

INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	SLT COUPLER DRIVER			
DESIGN	06-16-67	MS	TYPE	MOD 85
DETAIL	06-16-67	CPC	SCALE	NONE
CHECK	06-21-67	RMA	DATE	7090
APPROD	06-16-67	PMS	LoCoNo	5801447A