


STANDARD CODE	2-7246			9001041
CIRCUIT APPROVAL	PEC	02-03-64	STATUS	ACTIVE
LOCATION	MURLEY 140.6			RESTRICTED
RAW CARD NUMBER	8013566	2	HOLE PATTERN	8013566
FRONT NETWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
8013566	12-06-63	DEV1784		
BACK NETWORK	02-03-64	120880		
8013566	08-19-64	161445		

PIN	VOLTS
D 8	0ND
D 3	+ 3
B11	+ 6
B 5	- 3

CODE	PART NO	VALUE	QTY
Z 1	381427	SLT MODULE	8
A 1	2390656	RC MODULE	2
A 2	2414883	RC MODULE	3
A 3	2390625	RC MODULE	2

NOTES:

AA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.
 AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
 AC-CARD DOES NOT CONFORM TO DECOUPLING REQUIREMENTS IN 811800.
 AD-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.
 ADDITIONAL USAGE TO BE AVOIDED



-CONTACTS ON
 BACK OF CARD

INTERNATIONAL BUSINESS MACHINES CORP.					
TYPE	1	8 X 1/4 RECEIVERS			
DESIGN	09-13-63	CAB	TYPE	12040	
DETAIL	09-20-63	TC	SCALE	NONE	
CHECK	04-24-63	REL	DATE	17080	10-10-64
APPROD	02-03-64	TSC	SHEET	2 OF 3	