

STANDARDS CODE	2-6235	SHEET 2 OF 4	5803083
CIRCUIT APPROVAL	- -	STATUS	
LOCATION	RALEIGH		
RAW CARD NUMBER	5815572	HOLE PATTERN	5815572
FRONT ARTWORK	DATE	CHANGE NO.	DATE
3815572	03-18-66	160004	
BACK ARTWORK	09-12-67	172002	B
5815572			

PIN	VOLT.
008	GR
003	+12
B11	+12


CODE	PART NO	VALUE	QTY
Z 1	836442	SLT MODULE	1
Z 2	361493	SLT MODULE	8
Z 3	361494	SLT MODULE	4
Z 4	836441	SLT MODULE	1
A 1	2414883	RC MODULE	2

NOTES.

AA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.

AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913

AC-CARD DOES NOT CONFORM TO DECOUPLING REQUIREMENTS IN 811600.



INTERNATIONAL BUSINESS MACHINES CORP.					
NAME	HARPER ADDRESS AND RESET				
DESIGN	102-26-64	LRN	TYPE	1443	
DETAIL	103-10-64	RDE	SCALE	NONE	
CHECK	103-13-64	TH	DRAW	17090	09-05-67
APPRO	- -		LoCoNo		