



U03	AA4	0922	0523	I D12	09207	0721	0322	0523	I D05	03204	AK4	V 06	+09
				I D12 <td>09204</td> <td>AE4</td> <td>AG4</td> <td></td> <td>I B04</td> <td>03203</td> <td>0121</td> <td>V 09</td> <td>+09</td>	09204	AE4	AG4		I B04	03203	0121	V 09	+09
	AB4			I B13	09208	0321			I B07	03202	I D04	01202	Z2
	0922			I B12	09209	I B10	01204		N 03212	02A03	I B08	01203	V 13
	AC4			N 09212	08A03	I B09	07203	0322	02A1	N 03214	02A04	I D06	01207
	0922	08A1	N 09211	08A04	I D13	07207	I B07	05212	N 05202	03206	D 01201	03210	V 15
	I D10	09202	N 09204	09205	D 07210	09210	I B03	03209	D 03711	D02	D 01201	03210	V 16
	I D11	09203	D 09211	D07	D 07201	09210	I B05	03208	AD4		VOLTAGE		AT
	I D09	03205	AD4		AF4		I D05	03207	0121		Z1	V 02	+03

10 -17-63 DEV. 1740
8 -4-64 161163

RESTRICTED

TWO ONE WAY THRU FOUR WAY ADI
DATE 07-28-64 MACH. ASSEMBLY
LOG 143 FRAME
CD PG 1 OF 1 P.N. 05803195
IBM CORP. PD BLK. AP