

STANDARDS CODE	2-7045			5803215
CIRCUIT APPROVAL	GMR	07-27-64	STATUS	ACTIVE
LOCATION	POLYMERPSIF			RESTRICTED
RAW CARD NUMBER	5814176	1	MULE PATTERN	5814176
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5814176	11-01-64	DEV2135		
BACK ARTWORK	08-11-64	161303		
5814176				

PIN	VOLTY.
D 8	GND
D 3	+ 3
B 11	+ 6
B 6	- 3

CODE	PART NO	VALUE	QTY
Z 1	361408	SLT MODULE	6
Z 2	361409	SLT MODULE	3
Z 3	361412	SLT MODULE	3
A 1	2390418	RC MODULE	6
A 2	2414883	RC MODULE	3
A 3	2390417	RC MODULE	3

NOTES.


AA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.

AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913

AM-CARD DOES NOT CONFORM TO DECOUPLING REQUIREMENTS IN 811800.

FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.


ADDITIONAL USAGE TO BE AVOIDED



+ 02
33 23
24 A 2

+ 02
48 23
16 A 2

02 +
63 23
8 A 2



CONTRACTS ON
BACK OF CARD

INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	CARD ASM RE ERROR LATCH			
	LAM			
DESIGN	09-11-63	ADD	TYPE	2070
DETAIL	09-11-63	ADD	SCALE	NONE
CHECK	09-13-63	ADD	DRAW	7090 09-25-64
APPRO	07-27-64	GMR	SHEET	2 OF 5