

STANDARDS CODE	2-7045			5803325
CIRCUIT APPROVAL		- -	STATUS	
LOCATION				
RAW CARD NUMBER	5815160		HOLE PATTERN	811370
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5815159	2	3-11-64	DEV2695	
BACK ARTWORK	4-22-64	160180		
5815161	2			






RESTRICTED

PIN	VOLT.
D 8	GRD
D 3	+ 3
B11	+ 6
B 6	- 3

CODE	PART NO	VALUE	QTY
Z 1	361427	SLY MODULE	10
A 1	2390468	RC MODULE	10
A 2	2414883	RC MODULE	3

NOTES.

- AA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.
 AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
 FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.
 ADDITIONAL USAGE TO BE AVOIDED



CONTACTS ON
BACK OF CARD

INTERNATIONAL BUSINESS MACHINES CORP.					
NAME	CARD ASA-10 MULTIPLEX				
RECEIVERS			LAP		
DESIGN	10-14-63	CDA	TYPE	501C	
DETAIL	10-14-63	CDA	SCALE	NONE	
CHECK	10-14-63	CDA	DRAW	7050	04-15-64
APPRO	- -		SHEET	2 OF 4	