




STANDARDS CODE	2-7045			5803472
CIRCUIT APPROVAL	E&E	10-21-64	STATUS	ACTIVE
LOCATION	SAN JOSE			RESTRICTED
RAW CARD NUMBER	5816781	1	HOLE PATTERN	5816781
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO
5816781	06-03-64	160288		
BACK ARTWORK	10-21-64	161677		
5816781				

PIN	VOLT.
DO3	+03
DO8	GR
B11	+06

CODE	PART NO	VALUE			QTY	
R 1	216440	560.000	.25	+	5	2
R 2	216443	750.000	.25	+	5	2
R 3	216427	110.000	.25	+	5	2
R 4	216445	1.000K	.25	+	5	2
R 5	317080	330.000	2.00	+	5	2
Q 1	2414806	1.34 PNP				2
Z 1	361497	SLT MODULE				1
A 1	2414920	RC MODULE				2
HB	811399					2

NOTES.

AA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.

AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913

AK-CARD HAS BEEN DECOUPLED 811800 IS NOT APPLICABLE.

FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.

ADDITIONAL USAGE TO BE AVOIDED

HB-ASSEMBLY WITH P/N 811399 (TO-5) SPACER.

INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	HIGH CURRENT SWITCH 1			
	LAW			
DESIGN	01-13-64	LAW	TYPE	1430 Y-0
DETAIL	01-13-64	LAW	SCALE	NONE
CHECK	01-16-64	JB	DRAW	7090
APPRO	01-16-64	SLS	SHEET	2 OF 3
				09-29-64