

STANDARDS CODE	2-7045			5803474
CIRCUIT APPROVAL	IF	08-10-64	STATUS	ACTIVE
LOCATION	SAN JOSE			RESTRICTED
RAW CARD NUMBER	5816790	1	HOLE PATTERN	5816790
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5816790	04-14-64	DEV2753		
BACK ARTWORK	08-31-64	161274		
5816790				

PIN	VOLT.
B11	+06
D08	GR
B06	-03
D03	+03

CODE	PART NO	VALUE	QTY
7 1	351473	SLT MODULE	4
2 2	361453	SLT MODULE	4
2 3	361454	SLT MODULE	2
2 4	361456	SLT MODULE	2
A 1	2414883	RC MODULE	3

NOTES.

AA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.

AB-ASSEMBLY TO ENGINEERING SPECIFICATION 890913

AC-CARD HAS BEEN DECOUPLED B11800 IS NOT APPLICABLE.

AD-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.

ADDITIONAL USAGE TO BE AVOIDED

07 08 09 10 23 118	07 08 09 10 43 118	07 08 09 10 63 118
06 11	06 11	06 11
05 12	05 12	05 12
04 03 02 01 11 2 1 FA 38103	04 03 02 01 6 2 3 FA 58103	04 03 02 01 1 2 1 FA 78103

07 08 09 10 23 93	07 08 09 10 43 93	07 08 09 10 63 93
06 11	06 11	06 11
05 12	05 12	05 12
04 03 02 01 12 2 2 FA 38 78	04 03 02 01 7 2 4 FA 58 78	04 03 02 01 2 2 2 FA 78 78

07 08 09 10 23 68	07 08 09 10 43 68	07 08 09 10 63 68
06 11	06 11	06 11
05 12	05 12	05 12
04 03 02 01 13 2 1 FA 38 53	04 03 02 01 8 2 3 FA 58 53	04 03 02 01 3 2 1 FA 78 53

07 08 09 10 23 43	07 08 09 10 43 43	07 08 09 10 63 43
06 11	06 11	06 11
05 12	05 12	05 12
04 03 02 01 14 2 2 FA 38 28	04 03 02 01 9 2 4 FA 58 28	04 03 02 01 4 2 2 FA 78 28

04 02 33 23 15 A 1

04 02 48 23 10 A 1

02 04 63 23 5 A 1

13 12 11 10 9 8 7 6 5 4 3 2	13 12 11 10 9 8 7 6 5 4 3 2	13 12 11 10 9 8 7 6 5 4 3 2
13 12 11 10 9 8 7 6 5 4 3 2	13 12 11 10 9 8 7 6 5 4 3 2	13 12 11 10 9 8 7 6 5 4 3 2

CONTACTS ON
BACK OF CARD

INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	LATCH			
DESIGN	08-13-64	RT	TYPE	360-20
DETAIL	08-13-64	RT	SCALE	NONE
CHECK	08-22-64	JH	DRAW	7090
APPRO	09-22-64	SMS	SHEET	2 OF 4