







STANDARDS CODE	2-6235		SHEET 2 OF 4	5803487
CIRCUIT APPROVAL	HIS	12-14-67	STATUS	ACTIVE
LOCATION	SAN JOSE			RESTRICTED
RAW CARD NUMBER	5816973	1	HOLE PATTERN	5816973
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5816973	08-05-64	161065		
BACK ARTWORK	10-23-64	161872		
5816973	01-05-68	173092	IC	

PIN	VOLT.
D03	+03
B06	-07
D08	GR
B11	+06

CODE	PART NO	VALUE	QTY
Z 1	361475	SLT MODULE	4
Z 2	361451	SLT MODULE	4
Z 3	361455	SLT MODULE	2
Z 4	836401	SLT MODULE	2
A 1	2390641	RC MODULE	1

NOTES.

- AA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.
- AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
- AL-CARD HAS NOT BEEN DECOUPLED. 811800 IS NOT APPLICABLE.



INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	4WAY GATED DECODER WITH HDB DL			
TRUT + PULLOVER ENTRY				
DESIGN	10-09-64	RT	TYPE	12314
DETAIL	10-09-64	RT	SCALE	NONE
CHECK	10-10-64	T	ORCL	7190 02-01-68
APPRO	10-10-64	SMS	L&C.N.	LAMINATED