

THIS ALD HAS BEEN HAND CHECKED AGAINST THE WIRING

000 36431

D13

B12

B13

D09

B03

B07

B10

001

002

003

004

005

006

007

890971

T03AA A1
3B-AA

T03AA A5
3C-AB

873401

T03AJ A9
3E-AC

T03AF A4
3F-AD

890971

T03AA B1
3H-AE

T03AA B5
3J-AF

873402

T05AB C1
3L-AG

T05AB D1
3M-AH

T05AB E1
3N-AJ

873410

T15AE A2
4B-AK

T15AE A6
4C-AL

873062

T61AP A3
5B-AP

T61AP A7
5C-AQ

873062

T61AP A4
6B-AT

T61AP A8
6C-AU

D10

D05

B09

B02

D12

D11

D02

B04

D06

D07

D04

B05

B08

AA4

AK4

AB4

AL4

AC4

AD4

AE4

AF4

AF4

AV4

AG4

AH4

AJ4

CARD SIZE 1-12 PAC
VOLTAGE PINS
3 +5V0B11 +3V0D03
6 -3V0B06 GND0D08
4 SPECIAL RESTRICTED
3
1

T03

07-24-64 160623

RESTRICTED

SUBREGISTER CONTROL
DATE 07-16-64 RACH. ASSEMBLY
LOG 322A FRAME
CD PG 1 OF 1 P. No. 5803643
IBM CORP. WTC BLK. AX

3
6
4
3
1
000