

STANDARDS CODE	2-7045	SHEET 2 OF 4	5803757
CIRCUIT APPROVAL	ASD	06-29-67	STATUS
LOCATION	SAN JOSE		RESTRICTED
RAW CARD NUMBER	5819392	1	HOLE PATTERN
FRONT ARTWORK	DATE	CHANGE NO.	DATE
5819392	02-24-65	163297	A
BACK ARTWORK	05-01-67	169949	B
5819392			

PIN	VOLTS
B11	+6
D08	GND

CODE	PART NO	VALUE	QTY
R 1	5301517	10.000 .25 + 5	6
R 2	216445	1.000K .25 + 5	5
L 1	2391124	3.9 U	6
Z 1	361472	SLT MODULE	3
Z 2	361459	SLT MODULE	3
A 1	2390301	RC MODULE	6
A 2	2391304	RC MODULE	9
A 3	2390477	RC MODULE	2
A 4	2414883	PC MODULE	1
FA			9

NOTES:


AA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.

AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913

AK-CARD HAS BEEN DECOUPLED 811800 IS NOT APPLICABLE.

FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.

ADDITIONAL USAGE TO BE AVOIDED



CONTACTS ON
BACK OF CARD

INTERNATIONAL BUSINESS MACHINES CORP.			
NAME	SAMPLE PULSE DRIVER		
DESIGN	06-13-67	HVM	TYPE 1800
DETAIL	06-13-67	HVM	SCALE NONE
CHECK	06-14-67	TEH	DRAW 17090
APPRO	06-15-67	SMS	L&C 06-15-67