


STANDARDS CODE	2-7043	SHEET 2 OF 4: 5803789		
CIRCUIT APPROVAL	WAR	11-21-64	STATUS	ACTIVE
LOCATION	ENDICOTT			RESTRICTED
RAW CARD NUMBER	5819066 1		HOLE PATTERN	5819066
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5819066	10-01-64	DEV4157		
BACK ARTWORK	11-17-64	DEV4236		
5819066	12-11-64	162563		

PIN	VOLT.
D 8	GRD
D 3	+ 3
B 11	+ 6
B 6	- 3

CODE	PART NO	VALUE	QTY
R 1	216445	1.000K ±25 %	5
Z 1	361453	SLT MODULE	4
Z 2	361455	SLT MODULE	4
Z 3	361454	SLT MODULE	2
R 1	2414883	RC MODULE	3

NOTES:
 RA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.
 AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
 AH-CARD DOES NOT CONFORM TO DECOUPLING REQUIREMENTS IN 811800.
 FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.
 ADDITIONAL USAGE TO BE AVOIDED



INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	LATCH CARD PKY			
	LAM			
DESIGN	--	TYPE	2030	
DETAIL	09-24-64	VPJ	SCALE	NONE
CHECK	09-29-64	WJR	DATE	12-07-64
APPRO	--	LoCNo	LAMINATED	