

01	02	58123
43123	03	04
	8	A 2

01 02 38 98 23 98 16 A 2	+ 02 53 98 9 A 3	01 02 78 98 63 98 1 A 1
07 08 09 10 23 93	07 08 09 10 43 93	07 08 09 10 63 93
06 15 16 11	06 15 16 11	06 15 16 11
05 14 13 12	05 14 13 12	05 14 13 12
04 03 38 78 02 01 17 2 1	04 03 58 78 02 01 10 2 1	04 03 78 78 02 01 2 2 1 PA
01 02 38 73 23 73 16 A 2	01 02 58 73 43 73 11 A 2	01 02 78 73 63 73 3 A 2
07 08 09 10 23 68	07 08 09 10 43 68	07 08 09 10 63 68
06 15 16 11	06 15 16 11	06 15 16 11
05 14 13 12	05 14 13 12	05 14 13 12
04 03 38 53 02 01 19 2 1	04 03 58 53 02 01 12 2 1	04 03 78 53 02 01 4 2 1
01 02 38 48 23 48 20 A 2	01 02 58 48 43 48 13 A 2	01 02 78 48 63 48 5 A 2
07 08 09 10 23 43	07 08 09 10 43 43	07 08 09 10 63 43
06 15 16 11	06 15 16 11	06 15 16 11
05 14 13 12	05 14 13 12	05 14 13 12
04 03 38 28 02 01 21 2 1	04 03 58 28 02 01 14 2 1	04 03 78 28 02 01 6 2 1

+ 02 33 23 23 A 3

+ 02 48 23 15 A 3

02 + 63 23 7 A 3

3	12	11	10	9	8	7	6	5	4	3	2
13	12	11	10	9	8	7	6	5	4	3	2

CONTACTS ON
BACK OF CARD

STANDARDS CODE	2-7045			5804059
CIRCUIT APPROVAL	GHA	08-21-64	STATUS	ACTIVE
LOCATION	POUGHKEEPSIE			RESTRICTED
RAW CARD NUMBER	5814869	2	HOLE PATTERN	5814869
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5814869	03-11-64	DEV2650		
BACK ARTWORK	09-09-64	161467		
5814869				

PIN	VOLT.
D 8	GND
D 3	+ 3
B11	+ 6
B 6	- 3

CODE	PART NO	VALUE	QTY
Z 1	361412	SLT MODULE	9
A 1	2390431	RC MODULE	1
A 2	2390417	RC MODULE	8
A 3	2414883	RC MODULE	4

NOTES.

- AA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.
- AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
- AM-CARD DOES NOT CONFORM TO DECOUPLING REQUIREMENTS IN 811800.
- FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.
- ADDITIONAL USAGE TO BE AVOIDED

INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	CARD ASM IOP DECODER 2ND LEVEL			
	LAP			
DESIGN	02-10-64	IDI	TYPE	2070
DETAIL	02-10-64	IDI	SCALE	NONE
CHECK	02-11-64	JDM	DRAW	7090 09-30-64
APPRO	08-21-64	GHA	SHEET	2 OF 5