

2DL 1 HF

404 1 HF

CONTACTS ON
BACK OF CARD

PIN	VOLT.	PIN	VOLT.	CODE	PART NO	VALUE	QTY
				DL 1	2414872	N 125	2
				U 1	216259	PROGRAM CAP	40

AA-ALL CIRCUITS MUST CONFORM TO ENG.SPEC. SHOWN ON SHEET 1.
AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
AC-CARD HAS NOT BEEN DECOUPLED. 811800 IS NOT APPLICABLE.
AD-BOND TO CARD SURFACE WITH SPEC. 1209. PART MUST NOT BE
SUBJECTED TO ANY LIQUIDS.
AE-HAND ASSEMBLE CONTACT. REFERENCE PROGRAM USING P.O. 811824
AS REQUIRED.

5804234