














STANDARDS CODE	2-6236	SHEET 2 OF 3	5804269
CIRCUIT APPROVAL	ASD	02-17-68	STATUS ACTIVE
LOCATION	SAN JOSE		RESTRICTED
RAW CARD NUMBER	5816901	01	HOLE PATTERN 5816901
FRONT ARTWORK	DATE	CHANGE NO.	DATE
5816901	07-20-64	160546	A
BACK ARTWORK	01-14-65	162766	B
5816901	02-23-68	173116	C

PIN	VOLT.
G11	+06
G06	-03
J08	GND
J03	+03

CODE	PART NO.	VALUE	QTY
Z 1	361451	SLT MODULE	21
Z 2	361479	SLT MODULE	1
Z 3	836402	SLT MODULE	1
Z 4	361473	SLT MODULE	1
A 1	2390491	RC MODULE	16
A 2	2414920	RC MODULE	3
FR			1

NOTES:
 AA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.
 AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
 AC-CARD HAS BEEN DECOUPLED 811800 IS NOT APPLICABLE.
 AD-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.
 ADDITIONAL USAGE TO BE AVOIDED

INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	TRACK PULSE COUNTER WITH			
DECODES	R			
DESIGN	06-10-64	JA	TYPE	2311
DETAIL	07-06-64	PPY	SCALE	NONE
CHECK	07-08-64	CEG	DRAW	17090
APPRO	07-08-64	SMS	LOC. No.	05-24-68
				ELIMINATED