













A
B
C
D
E
F
G
H
J
K
L
M
N
P



CONTACTS ON
BACK OF CARD

STANDARDS CODE	2-6236	SHEET 3 OF 51 5804606
CIRCUIT APPROVAL	950	11-17-67 STATUS
LOCATION	SAN JOSE	RESTRICTED
RAW CARD NUMBER	5819384	31 HOLE PATTERN 5819384
FRONT ARTWORK	DATE	CHANGE NO. DATE CHANGE NO.
5819384	10-20-64	160539 09-21-66 168624 10
BACK ARTWORK	03-04-65	163621 12-07-67 172669 1E
5819384	01-12-66	167082 10

PIN	VOLT.

CODE	PART NO.	VALUE	QTY
CR 1	2106333	ALS	6
RR 1	756043	NO-02 NC-00	6
FN	813198		48

NOTES:
AA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.
AB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
AL-CARD HAS NOT BEEN DECOUPLED. 811800 IS NOT APPLICABLE.
AN-CONTACTS PIN 813198 TO BE INSERTED BEFORE LIQUID PROCESS PER
ENG. SPEC. 8711830 REED RELAY ASSEMBLY TO BE HAND MOUNTED ON
CONTACTS AFTER LIQUID PROCESS.

INTERNATIONAL BUSINESS MACHINES CORP.			
NAME	SECOND LEVEL SWITCH		
DESIGN	109-12-66	TYPE	11-17-67
DETAIL	11-18-67	SCALE	1:1
CHECK	11-20-67	REV	17, 19
APPRO	11-20-67	SMS	160539