

STANDARDS CODE	2-6240		SHEET 2 OF 5	5804913
CIRCUIT APPROVAL	G-M	02-02-65	STATUS	ACTIVE
LOCATION	BOULDER			RESTRICTED
RAW CARD NUMBER	5814941	A	HOLE PATTERN	5814941
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5814941	04-29-64	DEV1801	08-08-67	106607
BACK ARTWORK	05-08-64	160492		
5814941	02-18-65	162941	1B	

PIN	VOLT.
DC9	+18
B11	+ 6
G11	+ 6
D08	2ND
J08	GND
B06	- 3
G06	- 3

CODE	PART NO	VALUE	QTY
C 1	383608	6x2 U	3
Z 1	361457	SLT MODULE	5
Z 2	361499	SLT MODULE	3
Z 3	836457	SLT MODULE	1
Z 4	836402	SLT MODULE	1
A 1	2390816	RC MODULE	6
A 2	2390573	RC MODULE	6
A 3	2414883	RC MODULE	3
RA			1

NOTES:
 AA-ALL CIRCUITS MUST CONFORM TO ENG-SPEC. SHOWN ON SHEET 1.
 AB-ASSEMBLE TO ENGINEERING SPECIFICATION, 890913
 AK-CARD HAS BEEN DECOUPLED 811800 IS NOT APPLICABLE.
 RA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO LITHOGRAPHAL.
 ADDITIONAL USAGE TO BE AVOIDED

08	07	06	05	04	03	02	01
48	128		2390816				83 128
							18 A 1

INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	CARD-ASP DELAY LINE TERMINATOR			
DESIGN	05-13-63	CDA	TYPE	177
DETAIL	05-13-63	CDA	SCALE	NONE
CHECK	- -		DATE	08-22-67
APPRO	- -		LOCN.	ILAMINATED