




STANDARDS CODE	2-6240		SHEET 2 OF 71 5804920
CIRCUIT APPROVAL	GMP	12-16-64	STATUS ACTIVE
LOCATION	BOULDER		RESTRICTED
RAW CARD NUMBER	5814962	61	HOLE PATTERN 5814962
FRONT ARTWORK	DATE	CHANGE NO.	DATE
5814962	- -		09-13-65 165556 F
BACK ARTWORK	02-26-65	163234	10-28-65 165604 F
5814962	04-13-65	163743 D	08-08-67 165658 D

PIN	VOLT.	PIN	VOLT.	CODE	PART NO	VALUE	QTY
B11	+ 6	G11	+ 5	Z 1	836402	SLT MODULE	1
D03	+ 3	G03	+ 3	Z 2	361429	SLT MODULE	9
B06	- 3	G06	- 3	Z 3	836459	SLT MODULE	1
D09	+18	D08	GND	Z 4	361459	SLT MODULE	1
J08	GND			A 1	2390785	RC MODULE	9
				A 2	2390589	RC MODULE	9
				A 3	2390728	RC MODULE	5
				A 4	2414963	RC MODULE	6
				A 5	2390716	RC MODULE	2
				A 6	2390201	RC MODULE	9
				A 7	2414993	RC MODULE	9
				PA			2

NOTES:
 RA-ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.
 RB-ASSEMBLE TO ENGINEERING SPECIFICATION 890913
 RC-CARD HAS BEEN DECOUPLED PER 800 IS NOT APPLICABLE.
 RD-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.
 ADDITIONAL USAGE TO BE ADVISED



INTERNATIONAL BUSINESS MACHINES CORP.			
NAME	CARD ASSEMBLY FINAL REV AND		
S.E.F.			
DESIGN	05-14-64	CDA	TYPE 7
DETAIL	05-14-64	CDA	SCALE NONE
CHECK	05-14-64	CDA	DRAW 17090 108-22-67
APPROD	12-16-64	GMP	LOCN. 5804920H LAMINATED