

STANDARDS CODE	2-6240	SHEET 2 OF 7: 5804927		
CIRCUIT APPROVAL	GMM	12-16-64	STATUS	ACTIVE
LOCATION	BOULDER			RESTRICTED
RAW CARD NUMBER	5814983	8	HOLE PATTERN	5814983
FRONT ARTWORK	DATE	CHANGE NO.	DATE	CHANGE NO.
5814983	12-30-65	165575	F 03-20-67	169244
BACK ARTWORK	06-17-66	167733	G 03-27-67	166542
5814983	10-14-66	168760	H	

PIN	VOLT.	PIN	VOLT.	CODE	PART NO.	VALUE	QTY
J08	GND	D08	GND	R 1	216450	1.600K ±25 + 5	4
D11	+06	B11	+06	R 2	216439	510.000 ±25 + 5	1
D06	-03	G06	-03	R 3	216422	56.000 ±25 + 5	1
D09	+18	D03	+03	C 1	2391064	220. P	8
				CR 1	2414891	CV	12
				CR 2	369203	DD	4
				Z 1	369690	182 MPV	4
				T 1	2414942	PULSE TRANSFORMER	4
				T 2	2414943	PULSE TRANSFORMER	4
				Z 1	361432	SLT MODULE	4
				Z 2	361481	SLT MODULE	2
				Z 3	361429	SLT MODULE	2
				Z 4	361482	SLT MODULE	1
				Z 5	361459	SLT MODULE	3
				Z 6	361431	SLT MODULE	1
				Z 7	361472	SLT MODULE	1
				A 1	2390771	RC MODULE	4
				A 2	2414949	RC MODULE	4
				A 3	2390835	RC MODULE	1
				A 4	2390480	RC MODULE	6
				A 5	2390897	RC MODULE	2
				A 6	2390500	RC MODULE	4
				A 7	2390839	RC MODULE	4
				A 8	2414883	RC MODULE	4
				A 9	2392600	RC MODULE	2
				A10	2390481	RC MODULE	4
				A11	2390848	RC MODULE	1
				A12	2390704	RC MODULE	1
				A13	2390467	RC MODULE	2
				A14	2390543	RC MODULE	1
				A15	2414920	RC MODULE	2
				A16	2390642	RC MODULE	1
				RA			9
				HB	811399	PTO-54 SPACER	104

NOTES:
 ALL CIRCUITS MUST CONFORM TO ENG. SPEC. SHOWN ON SHEET 1.
 ASSEMBLE TO ENGINEERING SPECIFICATION 890913.
 AK-CARD HAS BEEN DECOUPLED 811800 IS NOT APPLICABLE.
 FA-TECH LAB EVALUATION INCOMPLETE. PART SUBJECT TO WITHDRAWAL.
 ADDITIONAL USAGE TO BE AVOIDED.
 HB-ASSEMBLE WITH PIN 811399 PTO-54 SPACER.

INTERNATIONAL BUSINESS MACHINES CORP.				
NAME	CARD ASM PRE-AMP AND Z DRIVER			
DESIGN	12-16-64	W	TYPE	NY
DETAIL	12-16-64	W	SCALE	WAVE
CHECK	-	-	DATE	7090 103-11-68
APPRO	12-16-64	GMM	LOC. NO.	5804927 PL ILLUMINATED

