






DEC 28 1978

LOCATION	TYPE	W/L PARTIAL	TIME IN TOW	NO. OF HITS	REV.
L125	SA7673N	376-0006	11	4	B
L126	SA7673N	376-0010	7	16	2
L4	SA7676N	376-0026	7	19	1
L470.28	SA7676N	376-0008	7	16	5
L023.85	SA7676N	376-0007	13	5	B
L9	SA7676N	376-0102	7	16	1
L104.23	SA7675N	376-0097	8	16	4
L16	SA7606N	376-0055	7	16	1
L15	SA7602N	376-0066	7	16	1
L16.38	SA7632N	376-0095	7	16	2
L10.27	SA7608N	376-0081	7	16	2
L20.26	SA7615N	376-0068	8	16	4
L32.33	SA7626N	376-0158	8	16	2
L26	SA7610N	376-0003	7	16	7
L29	SA7674N	376-0006	7	16	1
L34	SA7615N	376-0067	8	16	1
L35	SA7612N	376-0073	8	16	1
L36	SA7620N	376-0006	7	16	1

COMP.	SIZE	TYPE	VL.	PART NO.	QTY
R1	100A	Yw	330-2018	1	
R2	1.8K	Yw	330-3018	1	
R3,4	220A	Yw	330-2022	2	
R5,6,11	10K	Yw	330-4010	4	
R7,12-15	47K	Yw	330-3067	1	
R9,10	2.2K	Yw	330-3022	2	
C16	47AF20V CER.		300-1047	1	
C1,13	15AF20V TANT		300-4022	2	
C2,3,5,6,7 8,9,14,15	.01AF CER.		300-1903	11	
XTAL	6.25MHZ		321-0014	1	

[illegible]



DEC 07 1978